



R2 Water Solution

Recycle Today For a Better Tomorrow

Sewage Treatment Plant

20 KLD STP -Technology MBBR

Renovation : July 2023

Project : Prayag Hospital & Research Centre

J-206/A1, J Block, Sector 41, Noida, Uttar Pradesh 201301



Front Bottom Side Sheet Rusted , Welding Break.





CCT TANK BRECK MS SHEET DUE TO RUST



MS SHEET 4 MM THK
WELD CCT TANK

FRP SHEET CRECK
FROM CCT TANK

Renovation Cutting of Old Sheet





Renovation:- Welding of 4mm thk Sheet



Remove : Old Paint & Rust



OLD TANK PIC



ent
पण



आपातकालीन

आपातकालीन
आपातकालीन

After



Now

Before



REMOVE OLD FRP







BEFORE



AFTER





Please feel free to contact undersigned
if any further clarification required.
For any assistance feel free to call
us on 9650-31-3155

Thanks & Regards

For R2 WATER SOLUTION

Nisha Upadhyay

Mob : 9650-31-3155

Add. Q19 Jamia Nager

New Delhi-10025

Email rws.sales01@gmail.com

